Show Me
CABLES
cables & connectors since 1995

STEP 1. ALL PARTS OF THE CONNECTOR ARE SHOWN.



STEP 2. STRIP THE CABLE INNER CONDUCTOR,DIELECTRIC,BRAID,AND JACKETAS SHOWN.



STEP 3. SLIDE THE SLEEVE ONTO CABLE INSERT INNER CONDUCTOR INTO THE CONTACT PIN AND SOLDER IT.



STEP 4. SLIDE THE PIN INTO BODY AND CRIMP